



CGT



8000Gs

18000Gs



- 1.
- 2.
- 3.
- 4.
- 5.
- 6.

	× mm× mm		r/min			Gs		mm	t/h	kW		
CGT- 3/5								1			0.37	
2CGT- 3/5	300× 500	100× 500						2	0.8 1.0	0.75	0.37	
3CGT- 3/5							3	0.55				
4CGT- 3/5								4			0.55× 2	
CGT- 4/8								1			0.55	
2CGT- 4/8	400× 800	100× 800						2	1.2 2.0	1.10	0.75	
3CGT- 4/8							3	0.75				
4CGT- 4/8								4			0.75× 2	
CGT- 5/10								1			0.55	
2CGT- 5/10	500× 1000	100× 1000	30	17	82	4000	12000	2	0.1 2.0	2.0 3.5	1.50	0.75
3CGT- 5/10								3				0.75
4CGT- 5/10								4				0.75× 2
CGT- 5/12								1			0.75	
2CGT- 5/12	500× 1200	100× 1200						2	4.0 7.0	2.20	1.10	
3CGT- 5/12			3	1.10								
4CGT- 5/12			4	1.10× 2								
CGT- 6/15								1			0.75	
2CGT- 6/15	600× 1500	100× 1500						2	7.0 10.0	4.00	1.50	
3CGT- 6/15			3	1.50								
4CGT- 6/15			4	1.50× 2								

